

CTI-ReprogV1.1.10-win-x86.exe 25.XX.XX.XX.bin 24.XX.XX.XX.bin
SDK Ver1.10.1000 FWf[X] FWm[] D[X] S[]
SDK_DATE 20260210
[Name] JPSP [Name] [Name]
[Att] unknown(0)

[INFO] Testing started
[INFO] Please be patient...
[TEST] Please be patient...
[TEST] Please be patient...
[TEST] 1% [=====]
[INFO] Previus test in progress...
[TEST] Previus test passed
[TEST] Previus test failed
[ERROR] Code:00000002
==> PRESS SAVE IMAGE <==
[TEST] 2% [=====]
[INFO] Internal executables in progress...
[TEST] Internal executables passed
[TEST] Internal executables failed
[ERROR] Code:00000003
==> PRESS SAVE IMAGE <==
[TEST] 3% [=====]
[INFO] Voltage measurement in progress...
[TEST] 12 volt supply passed
[TEST] 12 Volt supply failed
[ERROR] Code:00000004
==> PRESS SAVE IMAGE <==
[TEST] 4% [=====]
[INFO] Save image

Date: 28/01/2026
Time: 14:06:22
Device Model: 13R10
Device S/N: 125489
Com Port: 5
Baud Rate: 19200

Scan
Connect
Disconnect
START
STOP
RESET


Test Time: 15.4 s
Status: TESTING
Total Passed: 4
Total Failed: 4

Start Logging
Stop Logging
Save Image

Reprog@ - www.reprog.com.br - 2026
C.T.I v1.1.10

Resultado

Texto informativo



ou

